

测试报告 报告号: SHHG1507023293HA 日期: 2015-12-10 页码: 1 / 14

江苏万源新材料有限公司 镇江市丹徒区上党镇兴业路工业园

下列样品由客户提供及确认为:

产品名称 : 丙烯酸涂层铝箔

收样日期 : 2015年07月01日

测试时间 : 2015年07月01日至2015年12月10日

测试要求 : ASTM B117-2011 & ASTM D1654-2008

测试结论 : 测试结果供客户自行分析

通标标准技术服务有限公司 授权代表签署

顾 琳

部门主管





报告号: SHHG1507023293HA

日期: 2015-12-10 页码: 2 / 14

测试项目:

1. 测试样的预处理

腐蚀环境中涂漆或覆层试样评估的标准试验方法(ASTM D1654-2008)

预处理类型: 无划痕

2. 测试方法和要求:

盐雾喷射装置的标准操作规程 (ASTM B117-2011)

DEALY DELYCOME	1		
测试样数量	1个		
样品防护	无		
基材和涂层	基材:铝		
	涂层: 丙烯酸涂料		
样品清洗方法 (测试前)	用流动的清水冲洗		
样品清洗方法 (测试后)	使用温度不超过38℃(100℃)的清	洁、流动水进行清洗或浸洗	
	样品以去除表面沉积的盐,然后立即	使用清洁的压缩气体进行干	
	燥。		
支撑或悬挂方法	支撑在塑料支架上		
测试周期	3600 小时		
测试中测试中断原因及时间	无		
中间检查间隔	500 小时之后,每 100 小时		
中间检查结果	见测试结果		
配制盐溶液的盐和水的类型	氯化钠:分析纯级别		
	水: 去离子水		
盐溶液	按照质量,将 5±1 份的分析纯试剂级	别的氯化钠溶液在 95 份的	
	去离子水中。		
	要求	结果	
测试表面倾斜的角度	与垂线成 15~30°	30°	
测试温度	35℃±2℃.	35℃.	
盐雾沉降率	1.0~2.0 (mL/h)/80cm ²	1.4(mL/h)/80cm ²	
收集液 pH 值(23±3℃)	6.5~7.2	7.0	
收集液浓度或密度(25℃)	5±1 mass%或符合表 3 的密度	1.033	



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or a http://www.sgs.com/en/Terms-and-Conditions.apx and, for electronic format documents, subject to Terms and Conditions for Documents and the subject to Terms and Conditions for the initiation of the subject of

3st Building, No.889, Yishan Road, Xuhui District Shanghai, China 200233 中国 - 上海 - 徐汇区宜山路889号3号楼 邮编: 200233

t (86-21) 61402666*2013 f (86-21) 54500353 t (86-21) 61402666*2013 f (86-21) 54500353



测试报告 报告号: SHHG1507023293HA 日期: 2015-12-10 页码: 3 / 14

3. 评定结果:

腐蚀环境中涂漆或覆层试样评估的标准试验方法(ASTM D1654-2008)

3.1 方法 B—无划痕区域的评定

使用 ASTM D714 中的标准起泡照片对起泡的结果进行评级,使用 ASTM D610 对锈蚀的结果进行评 级。

样品编号	评级(根据表 1)	锈蚀类型(根据表1)
500 小时	10 级	/
600 小时	10 级	/
700 小时	10 级	/
800 小时	10级	/
900 小时	10 级	/
1000 小时	10 级	/
1100 小时	10级	/
1200 小时	10级	/
1300 小时	10级	/
1400 小时	10级	/
1500 小时	10 级	/
1600 小时	10 级	/
1700 小时	10级	/
1800 小时	10 级	/
1900 小时	10级	/
2000 小时	10级	/
2100 小时	10级	/
2200 小时	10级	/
2300 小时	10级	/
2400 小时	10级	/
2500 小时	10级	/



3st Building, No.889, Yishan Road, Xuhui District Shanghai, China 200233 中国・上海・徐汇区宜山路889号3号楼 邮编: 200233

t (86-21) 61402666*2013

t (86-21) 61402666*2013 f (86-21) 54500353



测试报告 报告号: SHHG1507023293HA 日期: 2015-12-10 页码: 4 / 14

2600 小时	10级	/
2700 小时	10 级	/
2800 小时	10级	/
2900 小时	10级	/
3000 小时	10级	/
3100 小时	10级	/
3200 小时	10级	/
3300 小时	10级	/
3400 小时	10级	/
3500 小时	10级	/
3600 小时	10级	/

表 1

表面锈蚀百分率
≤ 0.01
> 0.01% 且 ≤ 0.03%
> 0.03% 且 ≤ 0.1%
> 0.1% 且 ≤ 0.3%
> 0.3% 且 ≤ 1.0%
>1.0% 且 ≤ 3.0%
> 3.0% 且 ≤ 10.0%
> 10.0% 且 ≤ 16.0%
> 16.0% 且 ≤ 33.0%
> 33.0% 且 ≤ 50.0%
> 50 %
S: 斑点腐蚀
G: 一般腐蚀
P: 针尖腐蚀
H: 混合腐蚀



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and purisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's Seponsibility is transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company, Any unauthrorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate. **Dease contact us at telephone: ###.65518307.4443

3st Building, No.889, Yishan Road, Xuhui District Shanghai, China 200233 中国・上海・徐江区宜山路889号3号楼 邮编: 200233

t (86-21) 61402666*2013 f (86-21) 54500353



报告号: SHHG1507023293HA

日期: 2015-12-10 页码: 5 / 14

Annex

TABLE 3 Temperature versus Density Data

Temperature °C (°F)	Density, g/cm ³			
	4-percent Salt Concentration	5-percent Salt Concentration	6-percent Salt Concentration	
20 (68)	1.025758	1.032360	1.038867	
21 (69.8)	1.025480	1.032067	1.038560	
22 (71.6)	1.025193	1.031766	1.038245	
23 (73.4)	1.024899	1.031458	1.037924	
24 (75.2)	1.024596	1.031142	1.037596	
25 (77)	1.024286	1.030819	1.037261	
26 (78.8)	1.023969	1.030489	1.036919	
27 (80.6)	1.023643	1.030152	1.036570	
28 (82.4)	1.023311	1.029808	1.036215	
29 (84.2)	1.022971	1.029457	1.035853	
30 (86)	1.022624	1.029099	1.035485	
31 (87.8)	1.022270	1.028735	1.035110	
32 (89.6)	1.021910	1.028364	1.034729	
33 (91.4)	1.021542	1.027986	1.034343	
34 (93.2)	1.021168	1.027602	1.033950	
35 (95)	1.020787	1.027212	1.033551	
36 (96.8)	1.020399	1.026816	1.033146	
37 (98.6)	1.020006	1.026413	1.032735	
38 (100.4)	1.019605	1.026005	1.032319	
39 (102.2)	1.019199	1.025590	1.031897	
40 (104)	1.018786	1.025170	1.031469	



3st Building, No.889, Yishan Road, Xuhui District Shanghai, China 200233 中国・上海・徐江区宜山路889号3号楼 邮编: 200233

t (86-21) 61402666*2013 f (86-21) 54500353 e sgs.china@sgs.com



报告号: SHHG1507023293HA

日期: 2015-12-10 页码: 6 / 14

样品照片:

测试样品







测试后 (600 小时)



测试后 (500 小时)



测试后 (700 小时)





3st Building, No.889, Yishan Road, Xuhui District Shanghai, China 200233 中国・上海・徐江区宜山路889号3号楼 邮編: 200233

t (86-21) 61402666*2013 f (86-21) 54500353 t (86-21) 61402666*2013

f (86-21) 54500353



报告号: SHHG1507023293HA

日期: 2015-12-10

页码:7/14

测试后 (800 小时)



测试后 (900 小时)



测试后 (1000 小时)



测试后 (1100 小时)





3st Building, No.889, Yishan Road, Xuhui District Shanghai, China 200233 中国・上海・徐江区宜山路889号3号楼 邮編: 200233

t (86-21) 61402666*2013 f (86-21) 54500353 t (86-21) 61402666*2013



报告号: SHHG1507023293HA

日期: 2015-12-10 页码: 8 / 14

测试后 (1200 小时)



测试后 (1300 小时)



测试后 (1400 小时)



测试后 (1500 小时)





3st Building, No.889, Yishan Road, Xuhui District Shanghai, China 200233 中国・上海・徐江区宜山路889号3号楼 邮編: 200233

t (86-21) 61402666*2013 f (86-21) 54500353 t (86-21) 61402666*2013

f (86-21) 54500353 e sgs.china@sgs.com



报告号: SHHG1507023293HA

日期: 2015-12-10 页码: 9 / 14


测试后 (1600 小时)



测试后 (1700 小时)



测试后 (1800 小时)



测试后 (1900 小时)





3st Building, No.889, Yishan Road, Xuhui District Shanghai, China 200233 中国・上海・徐江区宜山路889号3号楼 邮編: 200233

t (86-21) 61402666*2013 f (86-21) 54500353 t (86-21) 61402666*2013



报告号: SHHG1507023293HA

日期: 2015-12-10

页码: 10 / 14

测试后 (2000 小时)



测试后 (2100 小时)



测试后 (2200 小时)



测试后 (2300 小时)





3st Building, No.889, Yishan Road, Xuhui District Shanghai, China 200233 中国・上海・徐江区宜山路889号3号楼 邮編: 200233

t (86-21) 61402666*2013 f (86-21) 54500353 t (86-21) 61402666*2013

f (86-21) 54500353 e sgs.china@sgs.com



报告号: SHHG1507023293HA

日期: 2015-12-10

页码: 11 / 14

测试后 (2400 小时)



测试后 (2500 小时)



测试后 (2600 小时)



测试后 (2700 小时)





3st Building, No.889, Yishan Road, Xuhui District Shanghai, China 200233 中国・上海・徐江区宜山路889号3号楼 邮編: 200233

t (86-21) 61402666*2013 f (86-21) 54500353 t (86-21) 61402666*2013




报告号: SHHG1507023293HA

日期: 2015-12-10

页码: 12 / 14

测试后 (2800 小时)



测试后 (2900 小时)



测试后 (3000 小时)



测试后 (3100 小时)





3st Building, No.889, Yishan Road, Xuhui District Shanghai, China 200233 中国・上海・徐江区宜山路889号3号楼 邮編: 200233

t (86-21) 61402666*2013 f (86-21) 54500353 t (86-21) 61402666*2013



报告号: SHHG1507023293HA

日期: 2015-12-10

页码: 13 / 14

测试后 (3200 小时)




测试后 (3300 小时)



测试后 (3400 小时)



测试后 (3500 小时)





3st Building, No.889, Yishan Road, Xuhui District Shanghai, China 200233 中国・上海・徐汇区宜山路889号3号楼 邮編: 200233

t (86-21) 61402666*2013 f (86-21) 54500353 t (86-21) 61402666*2013

f (86-21) 54500353

www.sgsgroup.com.cn e sgs.china@sgs.com



报告号: SHHG1507023293HA

日期: 2015-12-10

页码: 14 / 14

测试后 (3600 小时)



此照片仅限于随 SGS 正本报告使用

报告结束



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible a http://www.sgs.com/en/Erms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Erms-en-Document.aspx. Attention is drawn to the limitation of liability indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility to its Client and this document does not exonerate parties to a transaction from exercising all ring rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorize alteration, foregry or faisification of the content or appearance of this document is unlawful and offerers may be prosecuted to the fulled extent of the law. Unless otherwise stated the results shown in this test report referr only to the sample(s) tested and such sample(s) ar retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 144

3st Building, No.889, Yishan Road, Xuhui District Shanghai, China 200233 中国・上海・徐汇区宜山路889号3号楼 邮編: 200233

www.sgsgroup.com.cn e sgs.china@sgs.com